

TACAN RWY 07

TACAN LRF
Chan **29**

APCH CRS
058°

Rwy Idg 12,007
TDZE 310
Arprt Elev 312

AL-738 [USAF]

LITTLE ROCK AFB (KLR)

*** When ALS inop, increase CAT AB RVR to 55, vis to 1 mile; CAT CDE vis to 1½ miles.**
**** Circling not authorized S of Rwy 07-25.**

ALSF-1
(A1)

MISSED APPROACH: Climbing left turn turn to 3000 to intercept LRF R-342 outbound to HERCK and hold as published.

ATIS★ 119.175 251.1	APP CON/DEP CON 119.5 306.2	TOWER 120.6 269.075	GND CON 132.8 275.8	CLNC DEL 253.5
--------------------------------------	--	--------------------------------------	--------------------------------------	---------------------------------

ALTERNATE MISSED APPROACH: Climbing to 3000 fly runway heading until LRF 2 DME, then turn left heading 360°, EFC from ATC.

JACKSONVILLE
Chan 29 LRF

ATC will ensure SUA deconfliction.

ATC RADAR required for holding above 6000' or greater than 230 KIAS.

HOLD 6000 3200

1096 LRF 17

238° 058°

R-238

1800 058° (7.6)

R2403A

R2403B

ROCK LRF 5.4

(IF/IAF) HURKO LRF 13

EMERG SAFE ALT 100NM 4000

3000 LRF R-342

HERCK LRF 13

TACAN CUTUM 1

2.6

2.83° TCH 50

4.4 NM

0.5

MSA LRF 25 NM

2500

3200

090°

360°

ELEV	312	TDZE	310
-------------	------------	-------------	------------

CATEGORY	A	B	C	D	E
S-07*	980/40 670 (700-¾)		980-1½	670	(700-1½)
** CIRCLING	980-1 668 (700-1)		980-1½ 668 (700-1½)	1040-2¼ 728 (800-2¼)	1040-2½ 728 (800-2½)

ASSAULT STRIP
07-25
0.3° UP
3499 x 60

12,007 x 150

TWR

HIRL Rwy 07-25
TDZL/CL Rwy 25